# **SF TAPE**




#### General recommendations:

- During the installation observe the compulsory security standards wear protective gloves and work clothes with long sleeves.
- During transport and storage, protect against mechanical damage.


#### STEP > 1

Splitting the tape in such a way as to get the required shape.




## STEP 3

Forming the required shape.



### STEP > 5

Pouring of concrete mix in the prefabrication plant.




#### STEP 2

Bending the tape.




# STEP 4

Installation of SF tape elements on tables for production of prefabricated components.



### STEP > 6

Bending of SF tape and pouring of concrete mix on finished ceiling panel.



Copyrights in the catalog including all its concepts, individual cards, photographs and graphics belong to PARTEC SYSTEM Sp. z o. o. with its registered office in Poland, at 55-002 Kamieniec Wrocławski, Gajków, Swobodna 6, NIP 8961572931, REGON: 369182452. Reproduction, copyring or distribution in whole or in part, without the written permission of PARTEC SYSTEM Sp. z o. o., is prohibited. Legal basis - Polish law on copyright and related rights. (Journal of Laws No. 24/1994, item 83, as amended).